



MiEV computer diagnosis report

Date 03.26.2012

Customer Name

Mechanics Name:

Hämmerle

VIN code : J00000000000000000000
 Mileage : 11035,0 km
 Ladestand (Ansteuerwert) : 25,0 %
 Batteriekapazität : 41,3 Ah
 CPU-Betriebszeit : 876 hour

Comprehensive evaluation

As a result of the check, abnormality was not detected.

Please make sure that the re-check should be done with the amount of over 50% High-voltage battery charge.

1. On-vehicle computer communication check result

CAN bus line is OK.

2. DTC (Self diagnostic code) check result

No DTC(s)

Computer name	Result	Computer name	Result
WEGFAHRSPERRE	OK	4WS/Servolenkung	OK
ABS/ASC/ASTC/WSS	OK	SRS-AIRBAG	OK
Klimaanlage	OK	ETACS	OK
Messgerät	OK	Lenkwinkelsensor	-
EV-ECU	OK	BMU	OK
COMP&HTR	OK	OBC	-
MCU	OK	CMU1	-
CMU2	-	CMU3	-
CMU4	-	CMU5	-
CMU6	-	CMU7	-
CMU8	-	CMU9	-
CMU10	-	CMU11	-
CMU12	-		

3. High-voltage check result

All data is within limit of normal.

System	No.	Item	Result	System	No.	Item	Result
EV-ECU	201	Batterie-Gesamtspannung	OK	EV-ECU	202	Kondensatorspannung	OK
BMU	3	Max. Spannung Batteriezelle	OK	BMU	5	Min. Spannung Batteriezelle	OK
BMU	20	Flag Leckerkennung	OK				

4. ELC.water heater test result

No error